

The 1-Page Alignment Map

Find the hidden cause of vibration & short bearing life (>3,000 RPM)

Batnon.com – single-setup machining + in-process probing

⚙️ The problem on high-speed lines (>3,000 RPM):

- Bearing life drops 3–5× (3 months → 3–4 weeks)
- 6–12 stops/shift → \$800–\$2,000/day lost output
- **Root cause in >80% of cases:** 0.02–0.05mm misalignment at the **shaft–housing bore interface**.

📍 Three failure zones

Zone	Issue	Consequence
1	Shaft runout >0.02mm	Orbiting, heat, seal wear, noise within weeks
2	Housing bore tilt	Uneven roller loading → skidding → early spalling
3	Bearing seat ovality	Point loading, cage fracture, 3× shorter life

📖 Visual reference

Shaft → Bearing inner ring → Bearing outer ring → Housing bore

⚠️ Runout ↗️ Tilt ● Ovality

(Diagram: misalignment at each interface)

🔧 How we fix it (without redesign):

- Single-setup machining of housing bore + bearing seat
- In-process probing to verify coaxiality <0.01mm
- Alignment error reduced by >70% vs conventional methods

📊 Real OEM result – Packaging automation line

Vibration ↓53%

3.2 → 1.5 mm/s

Bearing life ↑4×

4–5 weeks → 20+ weeks

Stops/shift ↓80%

8–10 → 1–2

 **Quick check you can do today (no special tools):**

- Listen for cyclic whine or irregular noise at operating speed
- Check temperature difference between housing vs bearing seat – $\Delta T > 10^{\circ}\text{C}$ indicates misalignment
- If you have a dial indicator: measure shaft runout at operating temperature – target $< 0.01\text{mm}$. If $> 0.02\text{mm}$, you're in the high-failure zone.

 **Next step**

Click the link in our email to discuss a **free alignment audit** (remote or on-site), or reply with your highest-RPM machine type – we'll send a custom alignment target sheet.